



Figure 5

Very severe streambank erosion, shown in red above, are common on outside bends of the river upstream of the North Trailhead Access. Cattle were observed in and near the river and contribute to streambank instability and increased nutrient and bacteria loading.

Source of Figure 5 image: https://www.iowadnr.gov/Portals/idnr/uploads/riverprograms/plans/wtplan_westfork.pdf

Summit pipeline estimated route (in red) overlaid on Figure 5 from "West Fork Des Moines River Water Trail Plan, 2019".